

<b>Base</b>	<b>Too Long</b>
Al Udeid	Running track 56.6 ft too long; walking track was 85.5 ft too long; all has been adjusted
Ali Al Salem AB	Track was 264 feet too long
Davis-Monthan AFB	Running track is 2 feet too long
Fairchild, WA	Indoor walk track was 54 ft too long, 2 other tracks are
Fort Meade, MD	50 ft too long
Goodfellow, TX	Track 85 ft too long; base working with AFPC to notify FA
Hanscom, MA	Track 360 ft too long; base working with AFPC to notify
JBER - Elemendorf/Richardson, AK	2 tracks are too long; base working with CE for another verification of track lengths
JBLE - Langley, VA	Outdoor track 46 ft too long; base working with CE to verify measurements; upon remeasurment track is in
Kadena, Japan	The running track is 11.58 ft too long
Laughlin, TX	Track is 44.5 ft too long, this has been corrected
Malmstrom, MT	Indoor Running track is 58 ft too long, all other track are
Osan, ROK	Outdoor running track was 48 ft too long, walking track was 34 ft too long indoor track was 120 ft too long
RAF Alconbury, UK	Run track is 22 ft too long; walk track is 18 ft too long; This has now been corrected and the track was re-
Shaw, SC	Run track was 6 ft too long and walk track was 13.3 ft
Travis, CA	Run track is 96 ft too long; walk track is 49.8 ft too long
Volkel AB	Running track was 2 feet too long; this has been
	<b>COUNT: 17</b>